

Upgrade Report

Version: N20.11.27

Development - Defect - (1)

Case Title or Change	Release Notes	Case #	Suggested Test Plan
	In very specific circumstances within the lab environment the Noetica DSP module would fail to start up. This has been resolved.	25100	No test plan required for this change.